

■ 装備表

●:標準装備 △:オプション

販売型式名		GHL50		GHL55	GHL60		GHL65
区分		H3	BN3	H3	H3	BN3	H3
電源	三相200V	●	●	●	●	●	●
乾燥部	遠赤ヒートリサイクル乾燥方式	●	●	●	●	●	●
	ガンタイプバーナ	●	●	●	●	●	●
仕様装備	水分計	●	●	●	●	●	●
	大豆水分計	—	●	—	—	●	—
	お急ぎ乾燥	●	●	●	●	●	●
	省エネ乾燥	●	●	●	●	●	●
	張込量自動検出	△	△	△	△	△	△
	極小乾燥	●	●	●	●	●	●
	ムラ取り乾燥(大豆を除く)	●	●	●	●	●	●
I Q 張込	●	●	●	●	●	●	
対象作物	稲・麦・そば乾燥	●	●	●	●	●	●
	大豆乾燥	—	●	—	—	●	—